

Page Denied

DISSEMINATION CONTROL ABBREVIATIONS

NOFORN-	Not Releasable to Foreign Nationals
NOCONTRACT-	Not Releasable to Contractors or Contractor/Consultants
PROPIN-	Caution-Proprietary Information Involved
USIBONLY-	USIB Departments Only
ORCON-	Dissemination and Extraction of Information Controlled by Originator
REL . . . -	This Information has been Authorized for Release to . . .

National
Photographic
Interpretation
Center

~~Top Secret RUFF~~

21 NOVEMBER 1977

25X1

IMAGERY INFORMATION REPORT

SS-X-20 FIELD-DEPLOYED CREW TRAINING AT
KAPUSTIN YAR MSTC, USSR (TSR)

(TSR) Canvas-covered SS-X-20 vehicles probably involved in field-deployed crew training were seen at two areas within the Kapustin Yar Missile/Space Test Center SSM, USSR, [REDACTED] (Figure 1). The two areas (Figures 2 and 3) are about 3 nautical miles (nm) apart and 20 nm northwest of the rangehead. In addition to the observation [REDACTED] the westernmost area was also occupied [REDACTED] while the easternmost area was occupied [REDACTED]. A review of previous imagery of these areas revealed that the westernmost area was also occupied [REDACTED]. Both areas contain scrub trees and brush, making the presence of canvas-covered vehicles difficult to detect.

25X1

25X1

25X1

25X1

25X1

25X1

(TSR) Canvas-covered vehicles/equipment seen in the westernmost area (Figure 2) are as follows:

[REDACTED]--one SS-X-20 canister on a TEL/resupply vehicle, one probable TEL/resupply vehicle (empty), two probable MAZ-543 missile support vans (MSVs), three MAZ-543 vehicles, and one unidentified vehicle;

25X1

[REDACTED]--two SS-X-20 canisters, each on a TEL/resupply vehicle; two probable MAZ-543 MSVs; and four MAZ-543 vehicles;

25X1

[REDACTED]--one SS-X-20 canister on a TEL/resupply vehicle and four probable MAZ-543 vehicles; and

25X1

GEOGRAPHIC COORDINATES

48-41-07N 045-58-53E

COUNTRY CODE


UR

25X1


25X1

25X1

Top Secret RUFF

-one SS-X-20 canister on a
TEL/resupply vehicle and five probable MAZ-543 vehicles.

25X1

(TSR) The following canvas-covered vehicles/equipment were seen in
the easternmost area (Figure 3)  three SS-X-20 canisters,
each on a TEL/resupply vehicle; one probable MAZ-543 MSV; four MAZ-543
vehicles; and one unidentified vehicle.

25X1

 25X1

Page Denied

Next 2 Page(s) In Document Denied